

Exchangeable Tips for Laptop AC Adapter



Type	Included in	Output Voltage	Tips Size	Description	Fit for laptops
M1	EW3964 EW3965 EW3966 EW3967 EW3971 EW3973 EW3974	15.0V	φ6.3*3.0*10.7mm	Toshiba Satellite (Pro) series, NEC Versa	Toshiba Satellite A8,A10,U100 series;P10 Series; P15 Series; P20 Series; P25 Series Satel-lite 1400 series; Satellite 1800 series; Satellite 2430 series; 2500;Satellite 5000 series;Satellite 5100 series; Satellite 5110; Portege 2000; Por-tege 2010; Portege 3500; Portege 3500 Tablet PC Portege 3505 Tablet PC Portege 4000;Portege 4010; Tecra 9000; Tecra 9100 series;Toshiba Tecra A4, M1,M2, S1,TEZ100,TEZ300 series; Satellite Pro, Pro 6000, Pro M10, Pro M15,Pro A30, Pro A120, Pro 300, Pro 400, Pro 450 Series;
M2		16.0V	φ5.5*2.5*10.7mm	IBM Thinkpad, Lenovo	All IBM Thinkpad A/R/T/X series
M3	EW3964 EW3965 EW3966 EW3967 EW3971 EW3973 EW3974	16.0V	φ6.0*4.4*10.7mm pin1.4	Panasonic, Sony, Fujitsu	SONY VAIO PCG-705, VAIO PCG-707,VAIO PCG-A,VAIO PCG-B,VAIO PCG-C,VAIO PCG-E, VAIO PCG-F, VAIO PCG-S,VAIO PCG-FX, VAIO PCG-GR,VAIO PCG-NV,VAIO PCG-QR,VAIO PCG-R505,VAIO,PCG-Z505, VAIO PCG-XR,VAIO PCG-FS,VAIO PCG-CR,VA10 PCG-FE,VAIO PCG-FZ,VAIO PCG-FJ series; Fujitsu LifeBook, and Stylistic series; Panasonic Toughbook CF series; FUJITSU Lifebook B,C, E,P,S series & Stylistic ST series
M4	EW3964 EW3965 EW3966 EW3967 EW3971 EW3973 EW3974	18.5V	φ4.8*1.7*10.7mm	Compaq, HP, LG	Compaq Evo Series ; N110 , N150,N200,N400c,N410c, N600c,N610c, N620c, N800,N800c, N800v, N800w; Compaq Armada Series ;110,110s, E300,E500, E500s,E700,M300,M500,M700,V300; Compaq Presario 900,1700, Z200, Z800,B1000,B2000,B3000, M2000, V1000,V2000, V2100, V2200,V2300, V2400, V2500, V2600, VZ700,V3000,V3100, V3300, V3300, V3400,V3500,V3600,V4000,V6000, V6100, V6200, V6300, V6400, V6500 HP Pavilion DV1000,DV1100, DV1200,DV1300,DV1400,DV1500,DV1600,DV1700, DV2000, DV2100, DV4000, DV6000,DV6100,DV6500, DV6600,DV8000,DV8200,DV8300,DV9000, DV9100, DV9200, DV9300, DV9400. DV9500, DV9600, DV9700,DV9800, DV9900, DX6600 Series ZT3000,ZT3200, ZT3300, HP Compaq ZE 2000, ZE2100,ZE2200,ZE2300,ZE2400,X1000,X1100,X1200,X1300, X1400, X1500 Series Series; Tablet PC TC1000, TC1100, MZ000, TC4200 series;Business,Notebook nc4000, nc4010, nc4200, nc6000,nx6110, nc6120, nc6Z20, ix6Z30, nc8000, nc8230,nw8000,nwBZ00, nw8240, nx5000,nx6110,nx6125, nx7000,nx7010, nx8220,nx9000, nx9020,nx9030,nx9040 series
M5	EW3964 EW3965 EW3966 EW3967 EW3971 EW3973 EW3974	19.0V	φ5.5*2.5*10.7mm	HP, Compaq, Acer, Toshiba, Fujitsu, Gateway IBM, Dell, NEC, Delta, LiteOn, Asus, Lenovo	COMPAQ Evo N105,Evo N115,Evo N160,Evo N180,Presario700,800,1000,1010,1020,1030,1040,1050,1060,1070,1080,1090,1200,1210,1230,1240, 1250,1270,1280,1600,1620,1630,1640,1650,1670,1680,1690,1700,1800,2100,2110,2120,2130,2140,2150,2160,2170,2180,2190,2200 ,2500,2700, 2800,3000,3020,3070,3080series; HP OmniBook 2100,2105,2106,2120,3000,3100,4100,4150,500,510,6000,6000B,6000C,6100,700,7100,7150,900, 900B,XE,XE2,XE3 series;Pavilion 6000,n3000,n3100,n3400,n5000,XH series,XZseries,ZT,ZE series,Business notebook n1050v,nx9000,nx9005, nx9010,nx9008 series; ASUS V1J,V2Je,F3P,W7J,Z35L,S6F,M9A,M9V,M9J,M9F,A8F,F9F,A7J,7JC,W2V,W3V,W3N,W3000,WSF,WSV,U1F,USF, USA,X50,G1S,G2S,XS1R,A3H,A3Ac,A3Vp,A3Vc,A3E,A3G,A3N/L,A3Hf,A3Fp,A3Fc,A6Jm,A6Km,A6M,A6T,A6Ta,A7C,A7F,A7G, A7J,A7M, A7S,A7Tc,ABJp,ABJr,ABJs, ABM,ARSc,A9RP,A9T,F2J,F2Je,F3Ja,F3Jc,F3Jm,F3Jp,F3Jr,F3M,F3Sc,F3T,F3Tc,F9J,GI,G2,V1Jp,VXZ, W11c,W2J, WZPc,W3J,W7F,W7FP, F5R, R1E,U6E series; TOSHIBA Satellite A100,A110,A130,A135,A2000,A205,L100,L110,L15,L20,L25,L30,L35,L40,L45, M200,M30,M35,M45,M50,M55,M65,M70,P200, Pro A100,Pro L20,Pro M50,Pro M70,Pro L100,U300,U305,1000,1005,1115,1130,1200,1600, 1620,1640,17301750,1900,1905,1955series; Tecra L2 series;Qosmio F45 series; Equium A100, L100,M70 series; IBM/Lenovo IdeaPad 3000,Y300, Y310, Y400, Y430,Y500, Y510, Y530 series;Compal ACY13, APL10, APL11, BCL3Z, BCQ1Z, CL3Z,CQ1Z, CY13, APL10, PL11, TS30H series; BENQ Joye-book series;CLEVO 2700, 66 Series, 86Z, 86CE,98 Series; FUJITSU LifeBook A1010, A3110,C1211,C1320, C1410, C2010, C2110, C2111,C2210, C2220,C2230, C2240, C2310, C2320, C2330, E2010,E330,E380,E4010,E4010D,E6624,E6634,E6644,E6654,E6664,E7010, E7110,E8000,E8000D, E8010, E8010D, E8020, E8210,N3400,N3410,N3500,N3510, S6310, S2210, S6310,S6410,S2210, S57000,S70000,S7010,S7010D,S7011, S7020, S7025, S7110, T4010, T4010D,T4210, T4020, Amilo D6820, Amilo D8820, Biblio 4100L,N6110,N6220, V1010, FMV-BIBLO MG755,FMV-BIBLO NBxx Series DELL Inspiron 1000, 1200,1300,2200,3000, 3500, 3200, 7000,B120,B130,Latitude 110L series; GATEWAY Solo 400, Solo 450,Solo 600, W322, M320 series; AVERATEC 3000,3120, 3150, 3150H, 3150HD, 3150HS, 3150P,3150HW,3120V, 5110, 5110H, 5110Hx,5110P,6200,AV6200H60, AV6240, 6240series;
M6	EW3964 EW3965 EW3966 EW3967 EW3971 EW3973 EW3974	19.0V	φ 5.0*3.0*10.7mm pin1.0	Samsung	Samsung X / M / P / Q / R / V / V M / GT series
M7	EW3964 EW3965 EW3966 EW3967 EW3971 EW3973 EW3974	19.0V	φ5.5*2.1*10.7mm	Acer Travelmate series, Delta, HP, Gateway, Toshiba, LiteOn	Acer TravellMate Series:345T,347T,351TE,350TE,352TE,210(T,TER),211T,212(T,TE,TV),220,223(X,XC),225(X,XC,XV-Pro),230,233XC,240,260, 270(XV),280,290,330(T),340T,341T,342,350,351TEV,352TE,353(Te,TEV),522,524TXV,525(Te,TV),527TXV,528TE,529(TX,TXV,ATX),530, 551XV,600 (TER),602(TER),603(TER),604TER,610(TXV,TV,X),611(TXV,TC),612(TXV,TC),613(TXV,TC),613(TXV,TC),613(TXV,TC),620,630,730(TX,TXV),732 (TLV,TV),7 32(TLV,TV),734TL,735TLV,738TLV,739TLV,740.Aspire:1200,1680,2000,2001,2002,2003,2010,2012,2013,2014, 2016, 2020, 2021,2023, 2024,2025, 2026,3000.Extensa:355, 501, 501 DX, 502(D), 503(DX), 505DX, 506DX,600, 610, 700, 700T, 710(DX, T, TE), 711TE, 712 TE.TravelMate Series: 233LC, 233X, 233XV, 233XVI, 234LCi,2350, 2352, 2352LCi, 2353, 2353LC, 2352LCi, 2353LM,2353LMi, 2353NLC, 2353WLMi, 2354, 2354LC, 2354LCi, 2354LM, 2354LMi, 2355, 2355LCi, 370, 370TCi, 370Ti,370TMI, 71 LCi, 371 LMi, 371 TCI, 371 TCI XP, 371 Ti, 371TMI,372, 372LCi, 372LMI, 372TC,372TCi, 372Ti, 372TM, 372TMI,374, 374TCi, 6000, 6000LCi, 6001, 6002, 6002LCi, 6003LC,6003LCi, 6003LM, 6003LMI, 6004, 6004LC, 6004LCi,6004LMI, 8000, 8000LCi, 8000LMI, 8001, 8001LCib, 8002,8002 (LC, LCi, LCib), 8003 (LC, LCi, LCib, LM, LMi, LMib), 8004 (LCi, LCib, LM, LMi, LMib), 8005 (LCi, LCib, LMi,LMib), 8006 (LCi, LM, LMi, LMib).TravelMate Alpha: 550 (LC, LV, XV) , 551l (XV), a550(LC,LV, XV), a551(XV), C300 (Xci, Xci-G), C301(Xci, Xci-G),C302 (MXi, XMi, XMi-G), C310, K-550.AcerNote:350, 370, 355, 356, 850C, Light 350,Light 360,Light 370 (C, P, PC), 372, 373(+), 374, Light 380. Contura:3/20, 3/25, 3/25C,4/20, 4/25, 4/25C,4/25CX.Armada:4100,4110(D,T), 4120(T), 4124D,4125D,4130(T), 4131 (T), 4150 (T) , 4160 (T), 4210T, 4220T.Presario: 300, 900.Latitude: LX4100, XL4100D, LX4100T.Smart Step: 200, 250. Solo 1100, 1150, 1200, 1400, 1450, 2100, 2300, 2500, 3300, 3450, 3350, 5100, 9100, 9300, 9550, Solo 400L, 450L, 5300, 5350, 600L ThinkPad:315, 2611, 310, 310D, 310ED, 315, 315E series.ThinkPadI:1400type26111, i1410, i1411, i1412, i1416, i1417, i1433, i1434, i1435, i1436, i1450, i1451, i1452, i1454, i1470,i1472, i1476, i1478, i1500 type 2611, i1512, i1552 series.
M8	EW3964 EW3965 EW3966 EW3967 EW3971 EW3973 EW3974	19.5V	φ6.0*4.4*10.7mm pin1.4	Sony PCG GRS Series, Fujitsu	SONY VAIO PCG-S05 series, VAIO PCG-V505R, VAIO PCG-VX series,VA10 PCG-GR series, VAIO PCG-SR series; VAIO PCG-SRX Series,VAIO PCGZ1xx Series, VAIO VGN-TX, VAIO VGN-T, VAIO VGN-TZ, VAIO VGN-UX Series

M9	EW3971 EW3973 EW3974	19.5V	φ7.4*5.0*12.5mm pin0.6	Dell	Dell Inspiron: 1150, 1420,1501, 1520,1521,1720,1721, 1510, 5160, 6000, 6400, 8500, 8600, 9200,9300, 9400, 300m, 500m, 505m, 510m, 6000D,600m, 610m, 630m, 640m, 700m, 710m, E1405,E1505, E1705, 1427, 1425, 1525, 1545; Latitude:100L, 131L, D400, D410, D420, D430, D500, D505,D510, D520, D531, D540, D600, D610, D620, D630,D631, D640, D800, D810, D820, D830 D-Series Doc-king Stations XI, X300; Dell Precision: M20, M60,M65,M70,M2300,M4300; DELL STUDIO 15,17; Dell VOSTRO:1000, 1400, 1500, 1700; Dell XPS: M1210,M140,M1020, M1330,M1530
M10		20.0V	φ 7.3*7.4*8mm	Dell	Dell Inspiron: 2500, 2600, 2650, 3700, 3800, 4000, 4100, 5000, 500e, 7500, 8000, 8100; Latitude: C400, C500, C510, C600, C610, C800, C810, CPI233ST, CPI366, CPI D233, CPI D266XT, CPI D300XT, CPIA, CPIA300ST, CPIA366ST, CPIA366XT, CPIA400XT, CPIC333GT, CPIC400GT, CPIR, CPIR400GT, CPM, CPM166ST, CPM233ST, CPM233XT, CPT, CPTC333GT, CPTS500GT, CPTC, CPTS, CPTV, CPTV466GT, CPX, CPXH, CPXH500GT, CPXJ, CPXJ650GT, CS, CSR, CSI, CSX, X200, Xpi, XPI133ST, XPI75T, XPICD, XPIP100SD, XPIP120ST, XPIP133, XPI series.
M11		20.0V	φ7.9*5.5*12.5mm pin0.9	IBM, Lenovo	LENOVO 3000 Series: C100, C200, N100, N200, V100,V200; Z Series: Z60m, Z60t, Z61e, Z61m, Z61p, Z61t; IBM ThinkPad X Series: X60, X60s, X61, X60 Tablet;ThinkPad T Series: T60, T60p, T61, T61p T400 T500;ThinkPad R Series: R60, R60e, R60i, R61, R61e, R61
M12	EW3965 EW3966 EW3967 EW3971 EW3973 EW3974	18.5V	φ7.4*5.0*12.5mm pin0.6	HP	HP Compaq Business notebooks: nc2400, nc2400,nc4200,nc4400,nc6220,nc6230,nc6320,nc6400,nx6310,nx6315,nx6320,nx6325,nx7300,nx7400, 2210,2210b, 2510, 2510b, 2510p, 2710, 2710b,6510b, 6515b, 6710b, 6715b, 6715s, 6720t, 6910b,8510b,8510w,8710b,8710w,TabletPC TC4400; HP Pavilion DV2,DV3, DV4, DV5,DV6,DV7 series , Com-paq Presario CQ20, CQ40,CQ45, CQ50, CQ60, CQ70 series;HP G70 series
M13		19.0V	φ5.5*1.7*10.7mm	Acer Aspire series, Dell, LiteOn, HP	ACER AcerNote 330,350, 361, 368, 370, 500,850,950 series; Aspire 1200, 1410, 1640, 1650, 1680,1690, 2000, 3030, 3040, 3100, 3500, 3600,3610,3670, 3680, 4710,5000, 5030, 5040, 5050,5100, 5500, 5510, 5540, 5550, 5560, 5570, 5580,5590, 5600, 5610, 5620, 5630, 5650, 5670, 5680,5700,5720, 5900, 7100, 9100,9300, 9400, 9410,9500 series;Extensa 355,700,710,740,900,2000,2300, 2350, 2500, 2600, 2900, 3000, 3100, 4100,series; TravelMate 200, 210, 220, 230, 270, 290,340, 350, 360, 370, 380, 420,500, 510,520, ZL,530, 540, 550, 600, 610,720,730, 740,2300, 2400,2410,2420,2430,2450,2460,2480,2490, 3000,3010, 3040, 3200, 3210, 3220, 3240, 3270, 3280,330, 3300, 4000, 4100, 4150,4600, 4650,4670,5600,6000,6410,6460,8000, 8100, 8200, 8210,C100, C200, C210, C300, MS, ZF Series; Acer Note Light 350, 360,370,380,P100 Series; Ferrari 1000,3000, 3200,3400,4000,5000 series
M14		10.0V	φ4.8*1.7*10.7mm	Sony, Asus	ASUS:9.5V/2.315A,9.5V/3A,SONY:10.5V/1.9A
M15		12.0V	φ4.8*1.7*10.7mm	HP, Asus, Lcd	HP:12V/2.5A,12V/3.5A,ASUS:12V/3A
M16		14.0V	φ6.0*4.4*10.7mm pin1.0	Dell, Samsung	DELL:14V/3A SAMSUNG:14V/3A,14V/4A
M17		18.5V	φ4.8*1.7*10.7mm	HP, Compaq	Compaq Evo Series; N110, N150, N200,N400c,N410c, N600c,N610c, N620c, N800, N800c,N800v,N800w; Compaq Armada Series;110,110s,E300, E500,E500s,E700,M300, M500,M700,V300; Compaq Presario 900,1700, Z200, Z800,B1000,B2000,B3000, M2000, V1000, V2000,V2100,V2200,V2300, V2400, VZ500, V2600,VZ700,V3000,V3100, V3300, V3300, V3400,V3500,V3600,V4000,V6000, V6100, V6200,V6300,V6400,V6500Series;HP Pavilion DV1000,DV1100, DV1200, DV1300, DV1400, DV1500,DV1600, DV1700, DV2000, DV2100, DV4000,DV6000, DV6100, DV6500, DV6600, DV8000,DV8200, DV8300, DV9000, DV9100, DV9200,DV9300, DV9400, DV9500, DV9600, DV9700,DV9800, DV9900, DX6600 Series,ZT3000,ZT3200,ZT3300,HP Compaq ZE2000, ZE2100,ZE2200,ZE2300,ZE2400,X1000,X1100,X1200,X1300, X1400, X1500 Series;Tablet PC TC1000,TC1100, MZOOO,TC4Z00 series; Business Notebook nc4000, nc4010, nc4200, nc6000,nx6110, nc6120, nc6Z20, ix6Z30, nc8000, nc8230,nw8000,nw8Z00, nw8240,nx5000, nx6110, nx6125, nx7000, nx7010, nx8220, nx9000, nx9020, nx9030, nx9040 series
M18		12.0V	φ5.5*2.5*10.7mm	Acer, BENQ LCD	LCD/ACER,BENQ:12V/3.5A,12V/2A,12V/2.5A,12V/1A,12V/3A,12A/4A
M19		12.0V	φ4.0*1.7*10.7mm	Samsung, Kodak	SAMSUNG:12V/3.5A,KODAK:12V/2A
M20		19.0V	φ4.0*1.7*10.7mm	HP/Compaq Mini	HP:19V/1.58A
M21		20.0V	φ5.5*2.5*10.7mm	Lenovo, MSI Wind, Dell, Fujitsu, LS	LENOVO:20V/2A DELTA:20V/1.2A,IBM:20V/2A LG:20V/2A,MSI:20V/2A,LS:20V/3.25A
M24	EW3964	19.0V	φ2.5*0.7*11mm	Asus (Netbook)	ASUS:19V,2.1A Eee PC 1005HA,1008HA,1101HA,1104HA,1106H
M26		19.0V	φ3.0*1.1*10.7mm	Samsung	SAMSUNG Ultrabook:19V/2.1A
M27		19.5V	φ4.5*3.0*9mm pin0.6	DELL	DELL Ultrabook:19.5V/2.31A
M28		20.0V	φ11*4.6*12mm	LENOVO	LENOVO Ultrabook:20V/4.5A
M29		22.0V	φ3.5*1.35*11mm	Sharp	Sharp
M30		19.0V	φ4.0*1.35*11mm	ASUS	ASUS
M31	EW3965 EW3966 EW3967 EW3971 EW3973 EW3974	19.5V	φ4.5*3.0*9mm pin0.6	HP	HP Envy:19.5V 3.33A,19.5V 4.62A

Free Tip Service

If your laptop/notebook requires another tip then the tips which are supplied with this product, you can send a request for the right tip to Ewent (please check the tiplist in this manual). We cannot guarantee that we have the requested tip at all time. When available, our support desk will send the tip to you for free.

You can send your request for the tip to us by using the supportform on our website: <http://www.ewent-online.com>